




# **Dial Gauges**

- One Revolution Dial Gauges
- Standard Dial Gauges (0.01mm, 0.005mm, 0.001mm)
- Long Travel Dial Gauges (0.01mm, 0.05mm, 0.1mm)
- Miniature Dial Gauges (0.001mm, 0.005mm, 0.01mm)
- Back Plunger Type Dial Gauges
- Accessories
- Technical Data
- Marking Service




# **One Revolution Dial Gauges**

# 0.001mm and 0.01mm Z series

•

These are high-accuracy dial gauges with the pointer giving less than a full turn that can resist rigorous continuous
measurement. The long stem is made of stainless steel, is high in strength and is malfunction-free due to fastening.
The dial faces except No. 18 and 17B are easy to read with green and orange (dead zone)






	Specification	\ \			/				(unit: µm)			
	Model	Graduation (mm)	Range (mm) (Free stroke)	Reading	1/10 revolution	Indication error  /10 revolution 1/2 revolution One revolution To			Whole measuring	Retrace error	Repeatability	Measuring force less than (N)
	15Z	0.001	0.16 (3.0)	80 - 0 - 80	2.5	±3,	±4	_	range —	3	0.5	1.5
	15Z-SWF	0.001	0.16 (3.0)	80 - 0 - 80	2.5	±3	±4	_	_	3	0.5	1.5
	5Z-XB	0.001 /	0.14 (3.0)	70 - 0 - 70	2.5	±3	±4	_	_	3	0.5	1.5
	5Z	0.001	0.14 (3.0)	70 - 0 - 70	2.5	±3	±4	_	_	3	0.5	1.5
	18	9.001	0.16 (3.0)	80 - 0 - 80	2.5	±3	±4	_	_	3	0.5	1.5
	17Z	0.01	0.8 (7.0)	40 - 0 - 40	8	±9	±10	_	_	5	5	1.4
	17Z-SWA	0.01	0.8 (7.0)	40 - 0 - 40	8	±9	±10	_	_	5	5	1.4
	107Z-XB	0.01	0.8 (7.0)	40 - 0 - 40	8	±9	±10	_	_	5	5	1.4
	107Z	0.01	0,8 (7.0)	40 - 0 - 40	8	±9	±10	_	_	5	5	1.4
1	17B	0.01	0.8 (10.0)	40 - 0 - 40	8	±9	±10	_	_	5	5	1.4
N	🤛 15DZ 🔒	100.0	0.16 (3.0)	80 - 0 - 80	2.5	±3	±4	_	_	3	0.7	1.5
N	🤊 117Z	0.01	1.0 (7.0)	50 - 0 - 50	8	±9	±10	_	_	5	5	1.4
	47Z /	0.01	0.8 (4.0)	40 - 0 - 40	9	_	±13	_	_	6	5	1.4
$\bigvee$	47Z-XB	0.01	0.8 (4.0)	40 - 0 - 40	9	_	±13	_	_	6	5	1.4
	47SZ	0.01	0.8 (4.0)	40 - 0 - 40	9	_	±13	_	_	6	5	1.4
	196Z	0.01	0.8 (4.0)	40 - 0 - 40	10	±12	±15	_	_	6	5	1.4
N	<b>9</b> 147Z	0.01	1.0 (4.0)	50 - 0 - 50	9	_	±13	_	_	6	5	1.4
N	🤊 36Z	0.005	0.4 (3.0)	20 - 0 - 20	_	_	±10	_	_	5	5	1.4


Note- All Dial Indicatiors (except for 196Z) listed above have flat back as standard.

Note- Lug back Model No.: 47ZL, 47Z-XBL, 47SZL, 147ZL, 36ZL.

### Dimensions



### Dimensions 196Z



### Sizes

odel	A	В	C	D	F	F	G	н	1	K
Lug back type					_	·	<u> </u>			- '`
15ZL	60		18.5							33.5
15Z-SWFL	62.5		10.5	F0	14.5					36
5Z-XBL	69.4		30						42.9	
5ZL	66.4						4	6.5	49	39.9
18L	69.4	41.5	29	55	16.8	(20)				41.9
17ZL	65		18.5							38.5
17Z-SWAL	65									38.5
107Z-XBL	69.4			E2	1/15					42.9
107ZL	66.4			30	55	14.5				
17B	65	40.5	18.5			20(-)				38.5
117ZL	65	41.5	18.5			(20)				38.5
15DZL	69.4	41.5	23.7	66.5	15.5	(20)		7.6		36
47ZL	58.9		20				1	E 0		40.9
47Z-XBL	61.9		30	26	10	(45)	4	5.6	20	43.9
47SZL	41.1	20	0.7	30	13	(15)	2.5		32	23.1
147ZL	41.1		9.7				3.5	6.5		23.1
36ZL	60	41.5	18.5	53	14.5	(20)	4		49	33.5
	Lug back type  15ZL  15Z-SWFL  5Z-XBL  5ZL  18L  17ZL  17Z-SWAL  107Z-XBL  107ZL  17B  117ZL  15DZL  47ZL  47Z-XBL  47Z-XBL  147ZL  147ZL  36ZL	Lug back type  15ZL 60  15Z-SWFL 62.5  5Z-XBL 69.4  18L 69.4  17ZL 65  17Z-SWAL 65.4  107Z-XBL 66.4  17B 65  117ZL 65  117ZL 65  117ZL 65  147ZL 69.4  47ZL 58.9  47Z-XBL 61.9  47SZL 41.1  147ZL 41.1  36ZL 60	Lug back type  15ZL 60 15Z-SWFL 62.5 5Z-XBL 69.4 18L 69.4 17ZL 65 17Z-SWAL 65 107Z-XBL 69.4 107ZL 66.4 17B 65 40.5 117ZL 65 41.5 15DZL 69.4 47ZL 58.9 47Z-XBL 61.9 47SZL 41.1 147ZL 41.1 36ZL 60 41.5	Lug back type  15ZL 60 15Z-SWFL 62.5 5Z-XBL 69.4 18L 69.4 17ZL 65 17Z-SWAL 65 107Z-XBL 69.4 107ZL 66.4 17B 65 40.5 117ZL 65 117ZL 65 41.5 18.5 15DZL 69.4 41.5 29 48.5 30 30 41.5 29 48.5 30 30 30 30 41.5 30 30 41.5 30 30 30 41.5 41.5 30 30 41.5 41.5 30 41.5 41.5 41.5 41.5 41.5 41.6 41.6 41.6 41.6 41.6 41.6 41.6 41.6	Lug back type					

lote- ( ) indicates the model number of lug back and its size. Both lug back and flat back share the same size except for the items listed under column F.

22


JIS B 7503

### 0.001mm and 0.005mm


Standard Dial Gauges

### Dial Gauges are widely used manufacturing plants.

- The stem, made of SK quench hardened with strength, is malfunction-free due to fastening.
- The shock-proof mechanism prevents gears from damage due to shocks arisen by abruptly pushing up the spindle.
- The turning section of the outer frame sealed by the O-ring and the back inside sealed by the packing are water-proof and dust-proof in construction.
- The back is increased in strength by four screws, and the lug can be turned 90 degrees in the installation way.



Lug back



Specifications

Specificatio	is (unit:									(unit: µm)	
Model	Graduation	Range	Reading		lı	ndication erro	or		Retrace	Repeatability	Measuring
Wiodei	(mm) (mm)		neading	1/10 revolution	1/2 revolution	One revolution	Two revolutions	Whole measuring range	error	riepeatability	force less than (N)
5B-HG	0.001	1	0 - 100 - 0	2	±2	±3	±3	±3	2	0.5	1.5
5-DX	0.001	1	0 - 100 - 0	2.5	±3	±4	±4	±5	3	0.5	1.5
5B	0.001	1	0 - 100 - 0	2.5	±3	±4	±4	±5	3	0.5	1.5
5F	0.001	1	0 - 100 - 0	2.5	±3	±4	±4	±5	3	0.5	1.5
5-SWF	0.001	1	0 - 100 - 0	2.5	±3	±4	±4	±5	3	0.5	1.5
25	0.001	2	±0 - 100 - 100	4	±5	±6	±6	±7	3	0.5	1.5
25F-RE	0.001	2	±0 - 100 - 100	4	±5	±6	±6	±7	3	0.5	1.5
25S	0.001	2	0 - 100 - 0	4	±5	±6	±6	±7	3	0.5	1.5
55	0.001	5	0 - 100 - 0	5	±6	±7	±8	±10	4	1	1.5
55-DX	0.001	5	0 - 100 - 0	5	±6	±7	±8	±10	4	1	1.5
56	0.005	5	0 - 25 - 50	6	±10	±10	±12	±12	5	5	1.5

24


JIS B 7503


### 0.01mm

Standard Dial Gauges

### Dial Gauges are widely used manufacturing plants.

- The stem, made of SK quench hardened with strength, is malfunction-free due to fastening.
- The shock-proof mechanism prevents gears from damage due to shocks arisen by abruptly pushing up the spindle.
- The turning section of the outer frame sealed by the O-ring and the back inside sealed by the packing are waterproof and dust-proof in construction.
- The back is increased in strength by four screws, and the lug can be turned 90 degrees in the installation way.





0.01

0.01

0.01

0.01

±0 - 50 - 100

±0 - 50 - 100

±0 - 50 - 100

0 - 50 - 0

 Flat crystal Contact point

Flat back

(unit: µm)

1.4

1.4

1.4

1.4

5

5

Specifications Lug back

57-SWA

57

57F

57B

Model	Graduation	Range	Reading		lı	ndication erro		Retrace	Repeatability	Measuring force less	
iviouei	(mm)	(mm)	neauing	1/10 revolution	1/2 revolution	One revolution	Two revolutions	Whole measuring range	error	переатаршту	than (N)
107-HG	0.01	10	±0 - 50 - 100	6	±7	±8	±10	±10	4	5	1.4
107-DX	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107F	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107-SWA	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107-BL	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107F-RE	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107-LL	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107W	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	1.4
107F-T	0.01	10	±100 - 50 - 0	8	±9	±10	±15	±15	5	5	1.4
107-E	0.01	10	±0 - 50 - 100	8	±9	±10	±15	±15	5	5	initial pressure 0.4
17	0.01	1	0 - 50 - 0	8	±9	±10	_	_	5	5	1.4

 $\pm 9$ 

±9

±9

±10

±10

±10

±10

±15

±15

±15

±15

±15

±15

±15

±15

# **Long Travel Dial Gauges**


0.01mm, 0.05mm and 0.1mm




**Long Travel Dial Gauges** 

### Dial Gauges are widely used manufacturing plants.

- The stem, made of SK quench hardened with strength, is malfunction-free due to fastening.
- The shock-proof mechanism prevents gears from damage due to shocks arisen by abruptly pushing up the spindle.
- The turning section of the outer frame sealed by the O-ring and the back inside sealed by the packing are water-proof and dust-proof in construction.
- The back is increased in strength by four screws, and the lug can be turned 90 degrees in the installation way.





Specification	าร

Specifications (unit: µm											
Model	Graduation (mm)	Range (mm)	Reading		Ir	ndication erro		Retrace	Repeatability	Measuring force less	
Wodel				1/10 revolution	1/2 revolution	One revolution	Two revolutions	Whole measuring range	error	riepeatability	than (N)
207	0.01	20	±0 - 50 - 100	10	_	±15	_	±20	7	5	2.0
207F-PL	0.01	20	±0 - 50 - 100	10	_	±15	_	±20	7	5	2.0
207F-T	0.01	20	±100 - 50 - 0	10	_	±15	_	±20	7	5	2.0
207S-LL	0.01	20	±0 - 50 - 100	10	_	±15	_	±20	7	5	2.0
207S	0.01	20	±0 - 50 - 100	10	_	±15	_	±20	7	5	2.0
207W	0.01	20	±0 - 50 - 100	10	_	±15	_	±20	7	5	2.0
207WF-T	0.01	20	±100 - 50 - 0	10	_	±15	_	±20	7	5	2.0
307S	0.01	30	±0 - 50 - 100	14	_	±18	_	±25	7	5	2.2
307	0.01	30	±0 - 50 - 100	14	_	±18	_	±25	7	5	2.2
507	0.01	50	±0 - 50 - 100	15	_	±20	_	±35	9	5	2.5
509	0.05	50	±0-5-10	30	_	±100	_	±100	10	20	2.5
809	0.1	80	±0 - 5 - 10	50	_	±100	_	±100	_	35	2.5

JMAS 2001

# **Miniature Dial Gauges**


**JMAS 2003** 

### 0.001mm, 0.005mm and 0.01mm



Miniature Dial Gauges

These compact size dial gauges are equipped with small dial faces. They are especially useful for measuring jigs, in



 $\pm 13$ 

±13

±15

±15

±0-25-50

0 - 25 - 50

0.005

0.01

# **Back Plunger Type Dial Gauges**

### 0.01mm

• The back plunger dial gauge is characterized with easy handling since the spindle having the contact point moves in the direction perpendicular to the dial face and the gauge is more compact.

• The dial gauge of this type is convenient for use in achieving a parallelism of the table of the machine tool, with measuring jigs, in restricted areas and on locations where scale reading is difficult.






### Graduation: 0.01mm Range:

- Stem ø 8mm Contact point (X-112)
  - Reversed dial Contact point (X-112)

● Stem ∮8mm



Range:

	Specifications (u											(unit: µm)
Model Graduation Range Reading						I	ndication erro	Retrace	Repeatability	Measuring force less		
	Wodel	(mm)	(mm)		1/10 revolution	1/2 revolution	One revolution	Two revolutions	Whole measuring range	error	ricpcatability	than (N)
	196A	0.01	5	0 - 50 - 100	10	±12	±15	±20	±20	6	5	1.4
	196A-6	0.01	5	0 - 50 - 100	10	±12	±15	±20	±20	6	5	1.4
	196Z	0.01	0.8	40 - 0 - 40	10	±12	±15	_	_	6	5	1.4
	196B	0.01	5	0 - 50 - 100	10	±12	±15	±20	±20	6	5	1.4
	196B-T	0.01	5	100 - 50 - 0	10	±12	±15	±20	±20	6	5	1.4

1.4


1.4

# Replaceable Contact Point (Screw pitch M2.5 × 0.45mm)

# for Dial Indicators and Linear Gauges

### Ball Contact Point






Part No.	L(mm)	Material
X-1	9	Steel
X-103	3.5	Steel
X-105	5	Steel
X-107	7.5	Steel
X-112	12.5	Steel
X-125	25	Steel
XB-1	9	Carbide
XB-115	15	Carbide
XB-125	25	Carbide
XB-130	30	Carbide
XC-1	9	Ruby
XC-125	25	Ruby

### Ball Contact Point for Oil Proof type





Part No.	L(mm)	Material
X-2	9	Steel
XB-2	9	Carbide
XC-2	9	Ruby
X-2A	12	Steel
XB-2A	12	Carbide


### Special Contact Point




X-6








### Offset Contact Point




### Special Contact Point



### Spherical Contact Point

XS-1




Part No.	L(mm)	Material
XS-1	8	SKS3
XS-105	5	SKS3
XS-110	10	SKS3
XS-115	15	SKS3
XS-120	20	SKS3
XS-125	25	SKS3
XS-130	30	SKS3

# Replaceable Contact Point (Screw pitch M2.5 × 0.45mm)

# for Dial Indicators and Linear Gauges

### Flat Contact Point






XS-2	eries					
Part No.						

, ,	\ \			
Part No.	L(mm)	Material		
XS-2	8	SKS3		
XS-205	5	SKS3		
XS-210	10	SKS3		
XS-215	15	SKS3		
XS-220	20	SKS3		
XS-225	25	SKS3		
XS-230	30	SKS3		

### Taper Contact Point






XS-3series

Part No.	L(mm)	Material
XS-3	25	SKS3
XS-310	10	SKS3
XS-315	15	SKS3
XS-320	20	SKS3
XS-330	30	SKS3

### Plain Contact Point






XS-4series

Part No.	Material
XS-4	SKS3

### ■ Flat Contact Point






XS-5series

	Part No.	L(mm)	Material
٦	XS-5	5	SKS3
7	XS-510	10	SKS3

### Button type Contact Point





XS-6series

Part No.	Material
XS-6	SKS 3

### Contact Point set XS




\*\*XS is provided with setting table for XS-1 to XS-6 contact points, and a case Each type sold separately.

Part No.	Material
XS	SKS3

### Knife-edge Contact Point





Part No.	L(mm)	Material
XS-710	10	SKS3
XS-715	15	SKS3
XS-720	20	SKS3
XS-725	25	SKS3
XS-730	30	SKS3


Replaceable Contact Point

# Replaceable Contact Point (Screw pitch M2.5 × 0.45mm)

## for Dial Indicators and Linear Gauges

### Carbide Spherical Contact Point






Part No.	L(mm)	Material
XB-305	5	Carbide
XB-308	8	Carbide

### Carbide Flat Contact Point






Part No.		L(mm)	Material
XB-405	5	5	Carbide
XB-406	4	6	Carbide
XB-408	5	8	Carbide


### Carbide Plain Contact Point






Part No.	Material	
XB-505	Carbide	
		$ lap{I}$

### Needle Type Contact Point



### Carbide Flat Contact Point






VD-002	Carbit

### Carbide Knife-edge Contact Point








Part No.	Material
XB-707	Carbide

### Carbide Plain Contact Point







	Par	t No			Ma	aterial	
X	B-5(	06			Ca	arbide	
		$\overline{}$	_//	$\overline{}$		$\overline{}$	

	$\sim$		
Part No.	φ D (mm)	L(mm)	Material
XB-800	1	2	Carbide
XB-801	1.5	12	Carbide
XB-802	2	7	Carbide
XB-803	2	12	Carbide
XB-804	1	20	Carbide
XB-805	1.5	20	Carbide
XB-806	2	20	Carbide
XB-807	1	40	Carbide
XB-808	1.5	40	Carbide
XB-809	2	40	Carbide
Part No.	φ D (mm)	L(mm)	Material
XS-800	1	2	SKS3
XS-801	1.5	12	SKS3
XS-802	2	7	SKS3
XS-803	2	12	SKS3
XS-804	1	20	SKH
XS-805	1.5	20	SKH
XS-806	2	20	SKH
XS-807	1	40	SKH

# Replaceable Contact Point (Screw pitch M2.5 × 0.45mm)








M2.5×0.45


### Contact Point Joint

XT-5


To extend the contact point, simply add the contact point joint.


L #4 type #5 type  6 XJ-406 10 XJ-410 XJ-510 15 XJ-415 20 XJ-420 XJ-520 25 XJ-425 30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490 100 XJ-400			
10 XJ-410 XJ-510 15 XJ-415 20 XJ-420 XJ-520 25 XJ-425 30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490		φ 4 type	φ 5 type
15 XJ-415 20 XJ-420 XJ-520 25 XJ-425 30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	6	XJ-406	
20 XJ-420 XJ-520 25 XJ-425 30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	10	XJ-410	XJ-510
25 XJ-425 30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-470 75 XJ-470 80 XJ-480 90 XJ-490	15	XJ-415	
30 XJ-430 XJ-530 35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	20	XJ-420	XJ-520
35 XJ-435 40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	25	XJ-425	
40 XJ-440 XJ-540 45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	30	XJ-430	XJ-530
45 XJ-445 50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	35	XJ-435	
50 XJ-450 XJ-550 55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	40	XJ-440	XJ-540
55 XJ-455 60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	45	XJ-445	
60 XJ-460 XJ-560 65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	50	XJ-450	XJ-550
65 XJ-465 70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	55	XJ-455	
70 XJ-470 75 XJ-475 80 XJ-480 90 XJ-490	60	XJ-460	XJ-560
75 XJ-475 80 XJ-480 90 XJ-490	65	XJ-465	
80 XJ-480 90 XJ-490	70	XJ-470	
90 <b>XJ-490</b>	75	XJ-475	
**   *** ***	80	XJ-480	
100 <b>XJ-400</b>	90	XJ-490	
	100	XJ-400	






**SH-2** 





\*Length of the thread screw of XJ-406 is 5mm.

Dimensions of Dial Gauge




**Dimensions of Dial Gauges** 

Standard	0.00	1mm	0.005	mm						(mm)
Model	Α	В	С	D	Е	F	G	Н	I	J
5B-HG	60	41.5	18.5	53	14.5	20	4	6.5	49	8.0-0.022
5-DX	60	42.6	17	55.7	14.5	20	5	7	52	8.0-0.03
5B	60	41.5	18.5	53	14.5	20	4	6.5	49	8.0-0.022
5F	60	41.5	18.5	53	14.5	_	4	6.5	49	8.0-0.022
5-SWF	63	41.5	17.5	55	15	20	4	6.5	49	8.0-0.022
25	72	42	25	66.5	14.5	20	4	7.5	62.5	8.0-0.03
25F-RE	72	41	25	66.5	14.5	_	4	7.5	62.5	8.0-0.03
25S	60	42.6	17	55.7	14.5	20	5	7	52	8.0-0.03
55	73	52	25	66	17	20	4.5	7	62.5	8.0-0.03
55-DX	62	44.5	17	57	17	19.5	4.5	6.5	52	8.0-0.03
56	62	44.5	17	57	17	19.5	4.5	6.5	52	8.0-0.03


Standard	0.01	mm								(mm)
Model	Α	В	С	D	Е	F	G	Н	I	J
107-HG	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
107-DX	65	50.7	17	55.7	14.5	20	5	7	52	8.0 -0.03
107	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
107F	65	41.5	18.5	53	14.5	_	4	6.5	49	8.0 -0.03
107-SWA	68	41.5	17.5	55	15	20	4	6.5	49	8.0 -0.03
107-BL	65	41.5	18.5	53	14.5		4	6.5	49	8.0 -0.03
107F-RE	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
107-LL	65	_	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
107W	65	41.5	17.5	55	17	20	4	6.5	49	8.0 -0.03
107F-T	65	41.5	18.5	53	14.5	_	4	6.5	49	8.0 -0.03
107-E	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
17	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
57-SWA	65	41.5	18.5	55	15	20	4	6.5	49	8.0 -0.03
57	65	41.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
57F	65	41.5	18.5	53	14.5	_	4	6.5	49	8.0 -0.03
57B	65	41.5	18.5	53	14.5	_	4	6.5	49	8.0 -0.03

Long Travel 0.01mm 0.005mm 0.1mm (m										(mm)
Model	Α	В	С	D	Е	F	G	Н	I	J
207	90	41	25	66.5	14.5	20	/5	7.5	62.5	8.0 -0.03
207F-PL	90	41	25	66.5	14.5	_	5	7.5	62.5	8.0 0
207F-T	90	41	25	66.5	14.5		5	7.5	62.5	8.0 0
207S-LL	75	50.5	18.5	53	14.5	20	4	6.5	49	8.0 -0.03
207S	75	50.5	<b>1</b> 8.5	53	/14.5	20	4	6.5	49	8.0 -0.03
207W	75	50.5	17.5	55	17	20	4	6.5	49	8.0 0
207WF-T	75	<b>60</b> .5	17.5	55	17		4	6.5	49	8.0 0.03
307S	107	89	22	57	17.5	20	5	7	52	8.0 -0.03
307	102	46	22.8	75.6	17.5	21	5	8	72.5	8.0 -0.03
507	128	81.5	26.7	81.5	17.5	21.5	5.5	8.5	78.5	10.0 0
509	128	81.5	26.7	81.5	17.5	21.5	5.5	8.5	78.5	10.0 0
809	201.5	86.5	54	112	24	22.5	6	10	108	14.0 -0.03

Miniature	2 0 01	mm	0 005r	nm						(mm)
Milliage C	V.V		0.0001							(111111)
Model	Α	В	С	D	E	F	G	Н	- 1	J
\$S /	43.2	30.5	12.9	40.8	12.5	_	4	5.1	37	8.0 0
47	39.6	20	9.7	36	13	15	3.5	5.8	32	8.0 -0.03
<b>47F</b>	39.6	20	9.7	36	13	_	3.5	5.8	32	8.0 -0.03
57S	41.3	27.4	10	39	14	19	4	5.1	36.5	8.0 -0.03
✓ 36A	46.2	30.5	12.9	40.8	12.5	19	4	5.1	37	8.0 -0.03
36B	46.2	30.5	12.9	40.8	12.5	19	4	5.1	37	8.0 -0.03



			_//		~1		
Back Plung	jer 0.0	1mm				,	(mm)
Model	Α	В	С	D	Е	F	G
196A	44	38	9/	4.5	6.35	28.1	57
196A-6	44	38	9	4.5	6	28.1	57
			90				




ack Plunger 0.01mm									
Model	Α	В	С	D	Е	F	G	Н	I
196B	58.5	38	12.5	4.5	_	_	_	5.5	16.5
196B-T	58.5	38	12.5	4.5	_	_	_	5.5	16.5
196Z	58.5	38	12.5	4.5	_	_	_	5.5	16.5

# **Accessories for Dial Gauges**

# Outer dial plates

Accessories for Dial Gauges





(0-100-200)

0.01mm type

Continuous Dial A







Reversed dial A  $(\pm 200-100-0)$ 

(Applicable Models) 5B-HG, 5B, 5F, 5-SWF

- We can manufacture outer dials for other 0.001mm dial indicators. (examples: 25, 55, 55-DX)
- We can manufacture outer dials with counter clock wise numbering.

### (Applicable Models)

107-HG, 107, 107F, 107-SWA, 107-BL, 107F-RE, 107-LL, 17, 57-SWA, 57, 57F.

 We can manufacture outer dials for other 0.01mm dial indicators. (examples: 47, 57S, 36B)

# Continuous Dial A

(0-50-100)



(0-100-100)



(0-100-0)

Reversed dial A (±100-50-0)

### Color Caps











Yellow Green

To manage the measurement by dial gauges, caps with five different colors are available. They are attachable to standard dial gauges. (No. 5, 107, 15, 17, 18, 55, 56 and 25S)


### ● Spindle Lifting Lever (LL-1)




55DX. 25S. 56, 17Z. 15Z. 107W

107. 107F. 57. 57B. 57F. 17. 17B. 207S. 5B. 5F. 55.

### Spindle pull-up Release



Dial Gauge installable
107F-RE. R1-B.
25F-RE. R1-A.




Repair Tools

### Backs


The method of holding the dial gauge comes in two types; holding the stem and holding the lug of the back. However, the back may be replaced for convenience of holding.

### Center lug back



Part No.	Outer dia.	Dial Gauge installable
GB-1A	46.0	107. 107Z. 17Z. 57. 17. 17B. 5Z. 15Z. 207S. 207W. 18. 5B
GB-125	59.5	25. 55. 207
GB-1307	69.8	307
GB-1507	76.7	507. 509
GB-1809	105.0	809
GB-147	30.7	47. 47Z. 47SZ
GB-136	35.8	5S. 36A. 36B
GB-157S	35.3	57S
GB-1DX	50.2	55DX. 56. 107DX. 307S. 25S

### Plat back




GB-3A	46.0	107. 107Z. 17Z. 57. 17. 17B. 5Z. 15Z. 207S. 207W. 18. 5B
GB-325	59.5	25. 207. 55
GB-3307	69.8	307
GB-3507	76.7	507. 509
GB-3809	105.0	809
GB-347	30.7	47. 47SZ. 47Z
GB-336	35.8	5S. 36A. 36B
GB-357S	35.3	57S
GB-3DX	50.2	55DX. 56. 107DX. 307S. 25S

GB-3A

### O Post back






GB-4A	46.0	107. 107Z. 17Z. 57. 17. 17B. 5Z. 15Z. 207S. 207W. 18. 5B
GB-447	30.7	47. 47Z. 47SZ

### 4 Screw back






GB-5A	46.0	107. 107Z. 57. 17. 5B. 5Z. 17B. 15Z. 207S. 207W. 18	1,	`
GB-547	30.7	47. 47Z. 47SZ		
GB-536	35.8	5S. 36A. 36B	1	7
GB-557S	35.3	57S		Ī
				_

### 6 Adjustable back



	,	
3.5 6.5 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6 9.6	45° 45° 4411	

GB-6A	46.0	107. <b>/</b> 0 <b>/</b> Z. 57. 1 <b>7</b> . 5B. 5 <b>Z</b> .
GB-625	59.5	25. 55. 207
GB-647	30.7	47. 47Z. 47SZ
GB-636	35.8	5S. 36A. 36B
GB-657S	35.3	5,7\$
	1	



GB-7A 107. 107Z. 57. 17. 5B. 5Z. 17B. 15Z. 17Z. 18. 207S

# **Repair Tools**

### The tools in the table below are available either in a set or individually.

# 1 Case

Width  $\times$  Depth  $\times$  Height

5 Driver with handle

sufficiently.

Pliers

of bottom board.)

225mm × 180mm × 170mm

This is used to a fasten a thread which may be, at first, fastened with small

driver, but finally requires to be fastened

(For example, fastening of attaching screw



This is used to draw out a pointer. Insert the tip of this tool under the pointer, and push the spindle center with thread. The pointer can be drawn out

In this case, the center of pointer drawer should match with the spindle



**3** Hand drawer



This is used to draw out a hand of gauge. Extend a piece of thin paper between the hand and the dial face. Insert the tip of the tool under the hand, and draw it out in accordance with the principles of

### 4 Plus and minus driver set (six in a set)



○ No.2 (1.4mmW) ○ No.5 (2.9mmW) ○ No.4 (2.4mmW) ⊕ No.1 (5mmW) Select a driver which is suitable for the width of thread head and that of the slot. In particular, please avoid fastening or loosening a large thread using a small driver.

**6** Reamer and reamer holder




**(1)** Washing brush

This is used to enlarge holes for pointer, hand, or spindle center. Stand the reamer in a right angle with the plane, and bore the hole lightly, relaxing your finger as possible as you can.



This is an oil to be lubricated in the course of assembly.



**8** Tweezers

This is used to handle small parts such as hair spring, pointer or small thread.

**1** Blower

the lever.

Clock oil



Lubrication brush

This is used, in the course of assembly, to remove dusts sticked to the dial face and so on. When the brush at the tip is removed, this can be used as a pump to blow off dusts. Do not breathe upon the apparatus to blow off dusts.

This is used, in the course of assembly, to lubricate into the spindle center. Use care to lubricate only a small amount

(B) Crystal press fitter

This is used to fasten or loosen a pin or



This is used to remove sticks such as

old oil cake and dusts with washing.

Set a crystal on the pad. Then press the fitter from the above to reduce the outer diameter, and fit the crystal into the

- Over plate installer is for pressing the cover plate into either the outer frame of a plunger-type dial indicator or a levertype dial indicator.
- Includes 8 types of changeable frames.
- Changeable frame examples:
- 3 and 4: for lever-type dial indicators PC and PCN
- 4 and 5: for small dial indicators
- 6 and 7: for standard type 0.001mm and 0.01mm dial indicators 7 and 8: for long stroke dial indicators

Changeable frame sizes (mm):

# **Technical Data**

### Dial Indicators JIS B 7503: 1997 (Japan Industrial Standards)



М	Methods of measuring of performance							
N	o. Item	Measuring method	Illustration	Measuring instrument				
	Indication error	Holding the plunger of the dial gauge vertically and downward, carry out the following procedure setting the reading of dial gauge at the zero point.	Dial gauge	Micrometer head or lengh measuring instrument of 0.5µm or under in scale interval and instrumental error of ±1µm and supporting stand for the dial gauge of 0.001mm and 0.002mm in scale interval and 2mm or under in measuring range.  For other dial gauges from the above, micrometer head or length measuring instruments of 1µm or under in scale interval and ±1µm in instrumental error and measuring stand.				
2	Adjacent error	Press in the plunger 1/10 by 1/10 revolution up to two revolutions from the zero point, 1/2 by 1/2 revolution up to five revolutions and 1 by 1 revolution up to the end point of the measuring range after exceeding five revolutions and, returning back the plunger in the same state, read	Supporting stand  Micrometer nead or length measuring instrument					
•	Retrace error	the same measuring points as in the pressing in direction. Obtain the error from the error diagram made as a result of the reading in both directions(see Attached Fig.1).						
4	Repeatability	Applying the contact point vertically on the upper surface of the measuring stand, obtain the maximum difference between the indications at every times when the plunger is operated rapidly and slowly five times at an arbitrary position in the measuring range.	Supporting stand  Measuring stand	Measuring stand. Supporting stand.				
į	5 Measuring Force	Hold the dial gauge whose plunger is placed vertically and downward, transfer the plunger up-and-downward continuously and slowly to measure the measuring forces at the zero point, center and end point of the measuring range.	Supporting stand  Upper ulso spring ype indicating palance	Supporting stand. Upper dish spring type indicating balance (2g or under in scale interval) or force meter (0.02 N or under in sensitivity).				

### Dial Indicators JIS B 7503: 1997 (Japan Industrial Standards)

±15

±15

	Maximum allowable error of indication							(unit: μm)	
			Scale interval and measuring range						
			0.01mm	0.002mm		0.001mm			
	Measuring ra	Measuring range		2mm max.	Over 2mm, and less than 10mm	1mm max.	Over 1mm, and less than 2mm	Over 2mm, and less than 5mm	
	Retrace Error		5	3	4	7(3	3	4	
	Repeatability		5	0.5	1	0.5	0.5	1	
		1/10 revolution (1)	8	4	5	2.5	4	5	
		1/2 revolution	±9	±5	±6	±3	±5	±6	
	Indication	One revolution	+10	<del>4</del> 6	+7	+4	+6	+7	

±8

±4

±5

±6

±7

±8


±10

Note: (1) Adjacent error. Remark. The value in this table shall be at 20°C.

Two revolutions

Whole measuring range


Indication error diagram




# **Marking Service**

### To all our valued customers:

When you purchase any new PEACOOK gauges from us, we now offer an optional value adding free making services of Control Numbers directly onto gauges for your ISO needs; any other control needs and for planned future needs.





Numbers of characters — • Alpabet-Capital letters (26)

Caracters of making — ABCDEF .....XYZ

