WIRELESS DATA TRANSFER SYSTEM

Code	Description	Арј	plicable products			
7306-2	receiver	USB and RS232 connection ports, strong transmission signal, the maximum distance is 100m				
7306-1	mini receiver	USB connection port, for short distance (within 20m) or barrier-free area				
7306-20	transmitter	2638	digital calipers, digital depth gages and digital height gages (not for 1103, 1150)			
7306-30	transmitter	\$2000 • • • • • • • • • • • • • • • • • •	digital micrometers, digital three point internal micrometers (not for 3631, 3632, 3108, 3109, 3635)			
7306-40	transmitter	355	digital indicators			
		DE LE	digital protractors			



- 1) Single collection: press the read button once to collect the reading from measuring tool once.
- 2) Multi collection: press the read button once to start collecting readings from measuring tools continuously, press the button again to stop collecting. Total collection times and interval time can be adjusted.
- DISPLAY: data can be input to Excel as keyboard signal.

All data are displayed in the same column. Each measuring tool can be coded such as A, B, C, etc.





measuring tools code A, B, C

	A	B	C	D	E	P	G
1	10.88	A			-		
2	5.963	В	-			2	
3	50.03	C				1	
4	25.49	D					
5	50.05	C		-		13	
6	10.89	A					
7	25.51	D					
8	5,965	В	1	0			
9	10.87	A					
10	50.04	C					
11	25.05	D					
12	50.03	C					
13	5.963	В					
14	50.05	C	-			100	



■ CONNECTION: one receiver can be connected to 30 transmitters.

